

NAME OF THE DIVISION
NAME OF THE SUB DIVISION

DETAIL STATUS OF THE EXISTING RIVER/SALINE EMBANKMENT
SAMBALPUR IRRIGATION DIVISION, SAMBALPUR
SASON CANAL SUBDIVISION, KHETRAPUR

Name of the embankment	Category of the				Length in KM	Name of the Basin	Name of the River	District	Reach	Status of the Embankment (Reach wise)					Brief description about deficiency in parameter		
	CE	OAE	TRE	SE						TBL 'M'	Side Slope	Top Width 'M'	Revetment packing in M with location,	Spur in No with location			
2																	
Flood embankment cum Ring Road of Sambalpur Town from RD 3.000 to 7.000 K.M.		OAE			4.000		Mahanadi				150.83	1/1.5	15.20	4000			
Flood embankment of Haradlore U/S left Bank of bridge near Govintola in Sambalpur Town.		OAE			1.215		Haradlore				147.00	1/1.5	7.00				
Flood Embankment of Haradlore D/S Right Bank of bridge near Govintola in Sambalpur Town.		OAE			0.925					00 to 420	150.00	1/1.5	7.00				
Maitlore near village Baham		OAE			1.85		Maitlore	Sambalpur			155.39	01:01.5	3.5	0			
Kurasingha at Khaldhar of Naktideul Block		OAE			0.28		Tikira	Sambalpur			103.25	01:01.5	3.5	280			
LB of river Bheden near Barakhandia			TRE		0.15		Bheden	Sambalpur			96.82	01:01.5	3.5	0			
Lath of Kuchinda Block		OAE			0.35		Kharla	Sambalpur			100.75	01:01.5		350			
Tanmura under Kuchinda Block		OAE			0.27		Bheden	Sambalpur			104.5	01:01.5		270			
Bhadelbasa near vill. Jamankira		OAE			0.18		Bhadelbasanalla	Sambalpur			105.15	01:01.5		180			
Village Saida under Kuchinda Block		OAE			0.60		Bheden	Sambalpur			103.50			Protection wall.			
Bijagarh under Naktideul Block		OAE			0.55		Tikira	Sambalpur			150.74	01:01.5		550			
LB of river Bheden near Lasa			TRE		4.50		Bheden	Sambalpur			151.26	01:04		180			
RB of Tikira near Kanchanpur			TRE		0.30		Tikira	Sambalpur			101.60	01:01.5		0			
LB of river Tikira near Pitasarai			TRE		1.50		Tikira	Sambalpur			147.55	01:01.5		0			

Name of the embankment	Category of the				Length in KM	Name of the Basin	Name of the River	District	Reach	Status of the Embankment (Reach wise)							Brief description about deficiency in parameter
	CE	OAE	TRE	SE						TBL 'M'	Side Slope	Top Width 'M'	Revetment in M with location.	Spur in No with location			
LB of river Tikira near Uppermunda.	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17		
RB of river Tikira near village Batgaon			TRE		2.00	Brahmani	Tikira	Sambalpur		93.00	01:01.5		200	3			
RB of river Tikira near village Girschandrapur			TRE		0.78	Brahmani	Tikira	Sambalpur		103.78	01:01.5		0	7			
			TRE		0.15	Brahmani	Tikira	Sambalpur		103.70	01:01.5		80	1			

Counters signed

20.5.19
 ASSISTANT ENGINEER,
 SAMBALPUR CANAL SECTION,
 KHETRAPUR

ASSISTANT EXECUTIVE ENGINEER,
 SASON CANAL SUB-DIVISION,
 KHETRAPUR

20.5.19
 EXECUTIVE ENGINEER,
 SAMBALPUR IRRIGATION DIVISION,
 SAMBALPUR

20.5.19
 SUPERINTENDING ENGINEER,
 HIRAKUD DAM CIRCLE, BURLA

20.5.19
 COLLECTOR & DISTRICT MAGISTRATE,
 SAMBALPUR