

STATUS OF STORAGE /REQUIREMENT OF FLOOD FIGHTING MATERIALS FOR THE ENSUING FLOOD OF 2019

NAME OF THE DIVISION : KHURDA IRRIGATION DIVISION, KHURDA

Sl. No.	Description	Empty gunny bag (in	Sand (in Cum)	Bambo (in Nos)	Bullah (in Nos)	Bamboo Mat (in Sqm)	Remarks
1	2	3	4	5	6	7	8
A	Requirement of Flood fighting materials for the ensuing Flood 2019	128000	2265				
B	Flood Fighting Materials already available by 15.06.2019	128000	2265				
C	Location of storage of flood fighting materials						Name of the In-Charge of the stockyard Contact No.
1	BANKI SECTION						Sri Srimanta Kumar Tripathy.A E , Banki Irr. Section , Banki , 9937541102
a	Karabara		60				
b	Chakuleswar		50				
c	Jatamundia	5000	100				
d	Rajib		50				
e	Anuary Rest shed	7000	40				
f	Banki Section Office	25000	400				
	<i>Sub-Total (Banki)</i>	37000	700	0	0		
2	JANKIA SECTION						Sri Muralidhar Behera, A.E, Jankia Irr Section,Jankia, 9437114083
a	Golabai escape	9000	100				
b	Lekhanpur	0	150				
c	Section office, Jankia	5000					
d	Raipur	0	25				
e	Naikulapatna	0	100				
f	Saradhapur	0	100				
g	Gaudapatna	0	150				
	<i>Sub-Total (Jankia)</i>	14000	625	0	0		
3	KHURDA SECTION						Sri Pravas Pattanaik , J.E, Khurda Irr.Section, Khurda, 9040196319
a	Haladipada	10000	150				
b	Kaudiapur	3000	100				
c	Matiapada		100				
d	Nankera	5000	150				
e	Dholapatna(Badaput)	20000	200				
f	Section store	20000	0				
	<i>Sub-Total (Khurda)</i>	58000	700	0	0		
4	TANGI SECTION						Sri Pravas Pattanaik , J.E, (I/C) Tangi Irr.Section, Tangi, 9040196319
a	Section Office at Tangi	14000	120				
	<i>Sub-Total (Tangi)</i>	14000	120				
5	HANTUAD SECTION-I						Sri Jagdish prasad Sethi. A.E Hantuad Irrigation Section-1,Hantuad, 9437324374
a	Irrigation Colony, Banapur	5000	120				
	<i>Sub-Total (Banapur)</i>	5000	120	0	0		
	Grand Total	128000	2265	0	0		

-6-


 Executive Engineer
 Khurda Irrigation Division, Khurda