

**Embankment Inspection of Nuapada Irrigation Division, Date:-19.05.2020 as per EE, Nuapada Irrigation Division
913, (WE), (3), dtd-15.05.2020.**

Lr. No:-

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	Kokrijhore Nallah	Bargarh	Jharbandh	Padmapur	Right (0.50Km)	Kotna embankment (Embankment near village Kotna in D/S of Spillway of Jharbandh Irrigation Project.	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.
2	Mahanadi	Ong River	Bargarh	Jharbandh	Padmapur	Left (0.70Km)	Lergaon embankment (Embankment of river Ong near village Lergaon)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.

[Signature]
19/05/2020
Junior Engineer
Jharbandh Irrigation Sub-Division
Jharbandh

[Signature]
19/05/2020
Sub-Divisional Officer
Jharbandh Irrigation Sub-Division
Jharbandh

[Signature]
Block Development Officer
Jharbandh

[Signature]
19/05/2020
Executive Engineer
Nuapada Irrigation Division
Nuapada.

[Signature]
19/05/20
Sarapanch
Kumir G.P.

[Signature]
19.5.20
Rasana Sahu
P.S. Member
Kumir G.P.

[Signature]
19-05-2020
PRESIDENT
Mas Lergani Pani Panchayat
At. Lergaon Po. Shabu

[Signature]
19/05/20
SECRETARY
Mas Lergani Pani Panchayat
At. Lergaon Po. Shabu

[Signature]
19.5.20
Revenue Supervisor
Tahasil Office, Jharbandh

[Signature]
19/05/2020
Tahasildar
Jharbandh

Countersigned
[Signature]
16/5/2020
COLLECTOR
BARGARH