

**NOTE SHEET**

Collector & District Magistrate, Rayagada


Office circular No.WF-misc-flood -10/2021-11494


Dated-07.04.2021 of Engineer-In-Chief, Odisha,Bhubaneswar communicated to your good office vide this office letter No-527 (WE) dated-08.04.2021 may please be per used.

As per instruction of Engineer-in-Chief,(WR)Bhubaneswar,the River Embankments belonging to Rayagada District under Paralakhemundi Irrigation Division, Paralakhemundi has been verified by the Executive Engineer,Asst.Executive Engineer and Junior Engineer concerned along with the Tahasildar Gunpur and Gudari on Dated 20.04.2021 and Revenue Inspector, Jimidepeta on Dt-23.04.2021 as per programme and found in good condition. At present health status of river embankment is in good condition. Necessary Precautionary measures will be taken as per requirement to protect such river embankment during monsoon period.

The status of river embankment is prepared as per prescribed format and put up for kind countersignature.

  
Asst.Executive Engineer

  
Executive Engineer  
Paralakhemundi irrigation Division,Paralakhemundi.

  
Collector & District Magistrate, Rayagada

## STATUS OF RIVER &amp; NALLA /SALINE EMBANKMENT(RAYAGADA DISTRICT)

## STATUS OF EMBANKMENT HEALTH UP TO APRIL-2021 OF PARALAKHEMUNDI IRRIGATION DIVISION, PARALAKHEMUNDI

Sl. No.	Division	Length of existing River & Nalla Embankment in Km In Rayagada District					River & Nalla Embankment in good condition (Length in Km)					Balance length of River & Nalla embankment needs to be protected with nature of vulnerability (Length in Km.)					steps taken to protect such embankment
		C.E	O.A.E	T.R.E.	SALINE	TOTAL	C.E	O.A.E	T.R.E.	SALINE	TOTAL	C.E	O.A.E	T.R.E.	SALINE	TOTAL	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1	Paralakhemundi Irrigation Division	8.141	4.218	87.090	-	99.449	8.141	4.218	80.540	-	92.899	-	-	6.550	-	6.550	Embankment now in good condition

*[Signature]*  
30/04/2021  
Assistant Engineer  
Gunupur Irrigation Section  
Gunupur

*[Signature]*  
20/04/21  
Junior Engineer  
Nagavali Irrigation Section  
Gunupur

*[Signature]*  
30/04/21  
Assistant Executive Engineer  
Gunupur Irr. Sub-Division  
Gunupur

*[Signature]*  
30/04/2021  
Executive Engineer  
Paralakhemundi Irrigation Division  
Paralakhemundi

*[Signature]*  
30/04/21  
Superintending Engineer  
Southern Irrigation Circle- II  
Paralakhemundi

*[Signature]*  
30/04/2021  
Collector-cum-District Magistrate  
Rayagada

STATUS OF RIVER & NALLA /SALINE EMBANKMENT(GAJAPATI DISTRICT)																			
STATUS OF EMBANKMENT HEALTH UP TO APRIL-2021 OF PARALAKHEMUNDI IRRIGATION DIVISION, PARALAKHEMUNDI																			
Sl. No.	Division	Length of existing River & Nalla Embankment in Km In Gajapati District					River & Nalla Embankment In good condition (Length in Km)					Balance length of River & Nalla embankment needs to be protected with nature of vulnerability (Length in Km)					steps taken to protect such embankment	Remarks	
		C.E	O.A.E	T.R.E.	SALINE	TOTAL	C.E	O.A.E	T.R.E.	SALINE	TOTAL	C.E	O.A.E	T.R.E.	SALINE	TOTAL			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	Paralakhemundi Irrigation Division	0.000	7.104	3.039		10.143	0.00	7.104	3.039		10.143							Embankment now in good condition	Steps will be taken as and when required to protect the embankment

*[Signature]*  
30-04-21  
Assistant Engineer  
Kasinagar Irrigation Section  
Kasinagar

*[Signature]*  
20/04/21  
Assistant Engineer  
Paralakhemundi Irr. Section  
Paralakhemundi

*[Signature]*  
30/4/21  
Assistant Executive Engineer  
Paralakhemundi Irr. Sub-Division  
Paralakhemundi

*[Signature]*  
30/04/2021  
Executive Engineer  
Paralakhemundi Irrigation Division  
Paralakhemundi

*[Signature]*  
30/04/21  
Superintendent Engineer  
Southeast Irrigation Circle-II  
Paralakhemundi

*[Signature]*  
Collector-cum-District Magistrate  
Gajapati